

Sta. of Utah

DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program June 14, 2006

Supervisor _

Permit number: M/021/030

Time: 5:00 PM

Inspection Date: June 6, 2006



Mine Name: Bright 1 & 2

Operator Name: 3-H Landscape Products LLC

Scott Holt

2160 East Riverside Drive St. George, Utah 84790

Inspector(s): Doug Jensen Other Participants: None

Mine Status: Active Weather: Clear

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)	X	X	
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads,	IXI	\sim	
highwalls, shafts, drill holes)			
8. Water Impoundments			
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other			

Purpose of Inspection:

Inspected the site while in the area to document changes that have taken place since my last inspection on October 27, 2005.

Inspection Summary:

The footprint of the quarries appears to be relatively unchanged since my last inspection. Mining in the Autumn Red Quarry has established a $\sim 30^{\circ}$ highwall. The ultimate plan in this area will remove the hill that pit has been established in. The result of the hill removal will be that no highwall will be left when mining is completed.

To the south the Peaches & Cream/Lilac Quarry appear to be deeper but the footprint has not increased. Further south Purple Quarry appears to be relatively unchanged except that the shot material that was located in the pit a year ago has been removed. The footprint of the Peanut Brittle Quarrys (North & South) appears to have changed a little since my last visit.

All the quarries within this permit were GPS'd recently by Ed Ginouves of the BLM, so I did not duplicate his effort. A copy of his GPS information is included with this report. No photos were taken during this inspection tour.

Conclusions and Recommendations:

I will continue to monitor this site when I am in the area.

Inspection Date: June 6, 2006; Report Date: June 14, 2006

Page 2 of 2 M/021/030

Inspector's Signature

Jensen Date: 6/14/06

Directions to Site:

Refer to previous inspection reports.

dj:pb

cc:

3-H Landscape Products, Operator

Attachment: GPS

